



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: December 9, 2008

Reviewed: LK

Mine Name: Henefer Landfill	Permit Number: S/043/0027
Operator Name: Interstate Brick Company	Inspection Date: 12/04/2008
Inspector(s): Brett Gregory for Leslie Heppler <u>LK</u>	Time: 1:00 PM
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$179,960 - DEQ holds this bond. **Permit fee:** Current.

Purpose of Inspection: This was a routine annual inspection.

Inspection Summary: Photos are attached.

1. Division of Solid and Hazardous Waste DEQ to be cc'd.
- 12) It had been noted in the previous inspection of the site that the landfill should be operational by now. The landfill is currently active. The operator has a stockpile of mined clay adjacent to the pit that he is currently removing from the site. (see photographs).

Conclusions and Recommendations: Once the operator has completed the removal of the clay stockpile, he could then request approval of the alternate post mining land use of a landfill (as approved by DEQ), and closure of the permit. Note, the bond held by DEQ is for ultimate reclamation of the landfill. DOGM will continue to monitor this site when in the area.

Inspector's Signature

BG:vs

cc: John Hewitt

O:\M043-Summit\S0430027-HeneferLandfill\inspections\insp-12042008.doc



Landfill in operation by the county



Interstate Brick stockpile on top of land fill.



Another view of the entire stockpile



Active removal of clay material